



Rigging & Repair Prices

Container Repairs	
Replace left or right (#2) main flap	\$125.00
Replace left or right (#2) main flap plastic stiffener	\$35.00
Replace grommets on main or reserve (without stiffener)	\$7.00
Replace grommets on main or reserve (with stiffener)	\$35.00
Replace #5 main pin cover	\$80.00
Replace #3B reserve pin cover flap	\$80.00
Replace center (#1) main flap (without pinstripes)	\$150.00
Replace left or right ring cover (without embroidery)	\$65.00
Replace left or right riser cover tuck tab	\$35.00
Replace both leg pads (w/ spacerform)	\$100.00
Replace both leg straps	\$90.00
Resize MLW (Hip & Chest Ring Harness)	\$175.00
Resize MLW (without Hip & Chest Ring Harness)	\$200.00
Adjust Laterals	\$100.00
Replace Laterals	\$125.00
Replace chest strap (with chest rings)	\$70.00
Replace chest strap (without chest rings)	\$95.00
Replace Harness (using existing hardware)	\$450.00
Retrofit SkyHook (Non-nexGen Icon)	\$325.00
Replace BOC Spandex	\$60.00
Replace TSO Label	\$12.00



Rigging & Repair Prices

Canopy Repairs	
Reline sport canopy	\$95.00
Reline tandem canopy	\$115.00
Triathlon 4.0 modification	\$20.00
Canopy Patches (starting at:)	\$40.00

Rigging Loft Services	
Wash Container (not assembled)	\$75.00
Reserve Repack	\$85.00
Full assembly and pack	\$125.00
Main assembly and pack	\$35.00
Reserve assembly	\$30.00
Main repack	\$10.00
Canopy inspection (main or reserve)	\$25.00
Test Jumps (not charged if under warranty)	\$75.00
Rigging Loft Labor (per hour)	\$60.00